


CENTURY MINE MITIGATION STREAM MITIGATION PHOTOGRAPHS
Long Run



Photograph: 74
LRL-11: Unsuccessful coir log and live staking



Photograph: 75
LRR-2: Partially successful planting of riparian zone



Photograph: 76
LRR-3: Unsuccessful coir log and live staking



Photograph: 77
LRR-6: Successful bank grading



Photograph: 78
LRR-7: Partially successful coir log



Photograph: 79
LRR-9: Successful boulder and toe protection